



CASE STUDY NO 15

Scissor Lift Deck

QUICK FACTS

- Goal:** Fabricate scissor lift deck to original technical drawings specification.
- Solution:** Fabricate and paint scissor lift deck.
- Result:** Metal fabrication and paint scissor lift deck to client's complete satisfaction.

THE ISSUE

A B Equipment was contacted to replace one of the scissor lift decks that was badly damaged and worn. The safe working load for the scissor lift is 8 tonne.

THE RESOLUTION

Our Major Works team was engaged to perform the fabrication for the unit. Once the fabrication was complete, the unit was then painted. Our client provided all technical drawings for the fabrication as they built the original scissor lift in 1988.

The fabrication for the scissor lift deck took three weeks to complete.

Together **E**veryone **A**chieves **M**ore

AFTER PHOTOS



Together **E**veryone **A**chieves **M**ore